


KMR-7 Quick Start Manual



Multi-function display with NMEA multiplexer




Turning power ON/OFF

Turning power on by press  to switch on the unit with a “beep” sound

Turning power off by press and hold  key until the unit display turn off

Display brightness and contrast adjust

1. Short press the  key




2. Press  or  to adjust LCD display brightness.

3. Press  or  to adjust panel dimmer.

4. Press  key to confirm and exit.

Display modes

Press  or  key to call out the graphic mode selection box as shown below :




Use the arrow keys to select the desired display mode and press  key to confirm.


The display modes show the information input from 4 NMEA0183 ports or NMEA2000 port.




Compass screen



Wind screen




Navigation screen



Highway screen



AIS screen



Weather screen

For more detail please download the full manual from <http://www.onwamarine.com>